Product Division – Product Change Notice

Product Information

PCN Tracking Number	735-00005
Issue Date	2017-10-23
Product Part Number	BMD-300-A-R BMD-301-A-R BMD-350-A-R
Customer Part Number	Not Applicable

Change Contact

Contact	Rigado Product Support
Phone	+1 (971) 208-9870
Email	support@rigado.com

Change Information

Detailed Description of Change		Factory firmware updated to revision AE: • Change of RigDFU from v3.3.1 to v3.3.1
Method of identifying Changed Product		Product label firmware code updated to show "AE"
Change Class / Reason for Change		MINOR / Bug fixes, performance enhancements, no hardware changes
Anticipated Impact	Form	None
	Fit	None
	Function	Loading custom firmware via SWD/JLink: None from version AD Loading custom firmware via OTA and serial bootloader: None from version AD
	Quality	None
	Reliability	None

Change Schedule

Estimated Production Ship Date	2017-04-24
Supplier Qualification Plan Schedule	Not Applicable
Qualification Data Available	Not Applicable
Samples Available	Programming utilities available to load new firmware on existing modules via SWD/JLink and OTA/serial bootloader Contact support@rigado.com for details
Last Date of Manufacture of Unchanged Product	Standard Production: 2017-02-21 Orderable with MOQ 5Kpcs and full lead-time

Other Information:

Issues Fixed in RigDFU
- *moved to SDK12's system_nrf52.c, which includes Nordic Semiconductor errata 108*
- *added 2 second delay upon receiving activate and reset command*
- *added restart command to BLE protocol, which initializes system without requiring a reset*
- *removed extraneous app_error_checks, which were causing activation failures*

No changes to BMDware
No changes to S132 v3.1.0

Revisions

Rev 1	2017-10-23	Initial Release