

PCN Number:	20181022005.0	PCN Date:	October 26, 2018
Title:	Datasheet for TMS570LS20216, TMS570LS20206, TMS570LS10216 TMS570LS10206, TMS570LS10116, TMS570LS10106		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



**TMS570LS20216, TMS570LS20206, TMS570LS10216
TMS570LS10206, TMS570LS10116, TMS570LS10106**

SPNS141G – AUGUST 2010 – REVISED OCTOBER 2018

October 2018	Removed all references to the SIL3 certification. Since this product is not recommended for new designs, Texas Instruments has chosen not to renew the SIL3 certification. No changes have been made to form, fit or function of this part.	G
--------------	---	---

The datasheet revision has changed.

Device Family	Change From:	Change To:
TMS570LS20216, TMS570LS20206, TMS570LS10216 TMS570LS10206, TMS570LS10116, TMS570LS10106	SPNS141F	SPNS141G

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TMS570LS10116>

Reason for Change:

TI removal of the SIL3 Certification reference.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Texas Instruments has chosen not to renew the SIL3 certification. No changes have been made to form, fit, function, quality, or reliability of this product.

Changes to product identification resulting from this PCN:

None.

Product Affected:

S5LS10106ASPGEQQ1	S5LS10106ASPGEQQ1R	S5LS10106ASZWTQQ1	S5LS10116ASPGEQQ1
S5LS10116ASZWTQQ1	S5LS10206AGPGEQQ1R	S5LS10206ASPGEQQ1	S5LS10206ASPGEQQ1R
S5LS10206ASZWTQQ1	S5LS10216ASPGEQQ1	S5LS10216ASZWTQQ1	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com

