

February 14, 2013

To: Our Valued Customers

Attention: Procurement Manager

Subject: **PLC13007A – Product EOL/Obsolescence Notification**

In the previous notice, PLC13007, the LTB/WTHD Date was entered incorrectly for the X24645S8IZ-2.7, X24645S8IZ-2.7T1, X28C010W, and X28C512W. The date has been corrected in the attached table and appropriate changes have been made in Intersil's systems. For any questions regarding the availability of these devices, please contact your local Intersil Sales person.

You are hereby provided notice that the Intersil products included on the attached parts list are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB/WTHD date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP/OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the lists and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

*Jon Kline
GCCN Customer Relations Dept.
Intersil Corporation*

Exact Intersil Part # No other variation is being impacted.	Notice PLC13007A Issue Date	LTB / WTHD DATE	SHIP/ OBSOLETE DATE	Replacement/ Similar/ Re-Design
EL5131IWZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5131IWZ-T7A	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5192ACSZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5192ACSZ-T13	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5192ACSZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5192ACWZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5192CWZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5193ACSZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5193ACSZ-T13	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5193ACSZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5193ACWZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5193CWZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5197ACSZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5197ACSZ-T13	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5197ACSZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5293CSZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5293CSZ-T13	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
EL5293CSZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
ISL28176FBZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	EL8176FSZ/-T7
ISL28176FBZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	EL8176FSZ/-T7
ISL28276FBZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
ISL28276FBZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
ISL28276IAZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
ISL28276IAZ-T7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
ISL28276WR5345	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
ISL6537ACRZA	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL6537ACRZ/-T
ISL6537ACRZA-T	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL6537ACRZ/-T
ISL9216IRZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL94212INZ/-T
ISL9216IRZ-T	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL94212INZ/-T
ISL9217IRZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL94212INZ/-T
ISL9217IRZ-T	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL94212INZ/-T
QLX1000CSFP0228	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX1000CSFP0728	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX1000CSFP0730	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX1000CSFP0830	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX111MSFF4	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX111MSFQ4	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX111MSFX1D	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX111MSFX2	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX111MSFX2D	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX111MSFX4	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX4000CQSFP0730	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX4000CQSFP0732	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX4000CQSFP1028	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX4000CQSFP1226	13-Feb-2013	30-Aug-2013	13-Feb-2014	None

QLX4001CQSFP1028	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX411MQSF4	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
QLX4600MIBQ15	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
X24645S8IZ-2.7	13-Feb-2013	15-Jun-2013	13-Jan-2014	None
X24645S8IZ-2.7T1	13-Feb-2013	15-Jun-2013	13-Jan-2014	None
X28C010W	13-Feb-2013	15-Jun-2013	13-Jan-2014	None
X28C512W	13-Feb-2013	15-Jun-2013	13-Jan-2014	None
X5043S8I-4.5AT1	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
X9221AUSIZT1	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9241AUSIZT1
X9221AUSZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9241AUSZ
X9221AYSIZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9241AYSIZ
X9221AYSZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9241AYSZ
X9221AYSZT1	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9241AYSZT1
X9241AWSZT1S2705	13-Feb-2013	28-Nov-2013	28-Nov-2014	None
X9251TS24IZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9251US24IZ
X9251TV24IZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9251UV24IZ-2.7
X9251TV24IZ-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9251UV24IZ-2.7
X9252TS24IZ-2.7	13-Feb-2013	29-Mar-2013	13-Apr-2013	X9252US24IZ-2.7
X9252TV24IZ-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	X95840UV20IZ-2.7
X9252UV24IZ-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	X95840UV20IZ-2.7
X9259TS24IZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9259US24IZ
X9259TS24IZ-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9259US24IZ-2.7
X9259TS24Z-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9259US24Z-2.7
X9259TS24Z-2.7T1	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9259US24Z-2.7T1
X9259TV24IZ-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	None
X9271TV14IZ-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9271UV14IZ-2.7
X9271TV14IZ-2.7T1	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9271UV14IZ-2.7T1
X9271TV14Z	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9271UV14Z
X9317ZM8Z-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9313ZMZ-3 or X9C102SZ
X9317ZS8IZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9C102SIZ
X9317ZS8IZ-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9313ZSIZ-3 or X9C102SIZ
X9317ZS8Z	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9C102SZ
X9319US8IZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	X9319WS8IZ or ISL95310UIU10Z
X9400YV24Z-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL22444WV20Z
X9418WS24IZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL22343WV20Z
X9418WS24IZ-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL22343WV20Z
X9418WV24IZ-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL22343WV20Z
X9418WV24Z	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL22343WV20Z
X9418WV24ZT1	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL22343WV20Z-TK
X9420YV14Z	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL22414WV10Z
X9460KV14IZ	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL22102IV20Z
X9460KV14IZ-2.7	13-Feb-2013	30-Aug-2013	13-Feb-2014	ISL22102IV20Z