

MACOM

100 Chelmsford Street
Lowell, MA 01851
+1 978.656.2500

www.macom.com



27th Sept 2022

PCN-01583

Digi-Key Corporation
701 Brooks Ave South
Thief River Falls, Minnesota 56701

Subject: Additional assembly, testing and packaging sites.

Dear Valued Customer,

MACOM Technology Solutions has a goal of providing redundant manufacturing capability for increased surge capacity as well as an uninterrupted supply chain. In alignment with this goal, we are pleased to announce the additional assembly, testing and packaging sites for the parts listed in the next pages.

In addition to our current site, we planned to assemble, test and package the parts at two of our long-standing Contract Manufacturers. The first CM is Year 2000, which is located in Ho Chi Minh City, Vietnam. The second CM is Hana Semiconductor, which is located in Ayutthaya, Thailand. Both of the two CMs are valued, high-quality manufacturing partner for many MACOM products.

In accordance with MACOM Technology Solutions' customer notification policy, you are receiving this notice because you have purchased one or more of the products listed in the previous two-year period.

Please contact your local sales representative if you have any specific questions.

Sincerely

Tom Galluccio
Director, Product Marketing
thomas.galluccio@macom.com

Appendix I
Affected part numbers

Part Number	Part Number	Part Number	Part Number
MPN7320-C12	M5X5437	MPN7320-C11	MA4L401-134
9010RK-SP	MPN7380-C38	M4X2097	MA4M3030
M5X1552	901R4K-SP	902R0M	MA4P303-134
MLP7121-11	M2X3301	9090R0K-SP	MA4P505-131
MX52162-11	MX51508-11	910R4K	MA4P506-131
905R0K	M5X5961	912R0B-SPD	MA4P604-131
9130RK	9047RK-SP14	M3X2673	MA4P7493-134
9023RK-SPM	9062RK-SP	MCC50-20C	MADP-000165-01340W
911R5K-BSP3	9099RK	MMP7021-11	MADP-000890-013400
MEST2GFC-10-25	910R5K	MMD832-C11	MADPSD0073
90100RK-SPD	M3X3018	MA46452-134	MASW-004240-13170W
90100RM-30	90350MIN-SP51	MA46470-134	MAVR-000120-14110G
M2X9235	M5X2954	MA46471-134	MAVR-046457-0134AG
MX51986-11	MMR11R0K-SR1JKG0T	MA46473-134	MAVR-046461-01340W
911R5K	MX52078-13	MA46480-134	
902R0K-SP	MTR680R-SR3JNAG0T	MA47416-132	
MX40154-11	9029R0K	MA4E1076-1261	
MSS30-046-C15	M3X3024	MA4E1317	
M2X3488	MADP-051488-0DIE0W	MA4E1318-BEL	
M5X1184	MSD701-11	MA4E1319-1	
913R7K-BSP-3	MX50570-11	MA4E2054L-1261	
MGPN1503-C01A	MX50688-11	MA4E2502M-1246-PB	
MC2S022020-020	MX52164-11	MA4E2514M-1116	
MX51625-11	M5X5558	MA4E931Z2-1261A	
MMP7031-11	MCC100-10B	MA4FES1TNR	
MGS801	MX52270-11	MA4GP030-277	
MGV125-08	MMD840-C11	MA4L011-134	
MSS20-047-C15	MNM212-11	MA4L032-134	
9123RK	MPN7453A-C22	MA4L062-134	
MX50606-10	MADP-051267-0DIE0W	MA4L101-134	