



Final Product Change Notification

202010023F01

Issue Date: 09-Nov-2020

Effective Date: 07-Feb-2021

Here's your personalized quality information concerning products Digi-Key purchased from NXP. For detailed information we invite you to view this notification online

This notice is NXP Company Proprietary.



Management Summary

PCA9450 new die A1 version release to replace old die A0 version.

Change Category

- | | | | | |
|----------------------------------------------|---------------------------------------------|----------------------------------------------------|-----------------------------------------|---------------------------------------------------------|
| <input type="checkbox"/> Wafer Fab Process | <input type="checkbox"/> Assembly Process | <input type="checkbox"/> Product Marking | <input type="checkbox"/> Test Location | <input checked="" type="checkbox"/> Design |
| <input type="checkbox"/> Wafer Fab Materials | <input type="checkbox"/> Assembly Materials | <input type="checkbox"/> Mechanical Specification | <input type="checkbox"/> Test Process | <input type="checkbox"/> Errata |
| <input type="checkbox"/> Wafer Fab Location | <input type="checkbox"/> Assembly Location | <input type="checkbox"/> Packing/Shipping/Labeling | <input type="checkbox"/> Test Equipment | <input type="checkbox"/> Electrical spec./Test coverage |
| <input type="checkbox"/> Firmware | <input type="checkbox"/> Other | | | |

FPCN: PCA9450 New Die A1 Version Release.

Description of Change

Dear customer, NXP is replacing the current version of the die (A0) with an A1 variant. The PCA9450A will be replaced by introducing a PCA9450AA version, while the PCA9450B and the PCA9450C variants will utilize the A1 die. (the OPN for the AA version can be seen in the parts list, B & C will stay the same and get a rolling update)

Parts list:

PCA9450A replaced by the PCA9450AA (12NC: 9354 101 98518)
PCA9450B (no replacement)
PCA9450C (no replacement)

Reason for Change

NXP observed a "hump" which could occur on buck output voltage in the event when VIN supply is hot plugged off, with peak voltage of about 100mV, and the duration is shorter than 120us. The new version A1 resolves such behavior on buck output.

Identification of Affected Products

Product identification does not change

Product Availability

Sample Information

Samples are available upon request

Production

Planned first shipment 22-Nov-2020

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No impact on form, fit, function, reliability or quality.

Data Sheet Revision

A new datasheet will be issued

Disposition of Old Products

Existing inventory will be shipped until depleted

Timing and Logistics

In compliance with JEDEC J-STD-046, your acknowledgement of this change is expected by 09-Dec-2020.

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name Wenfeng Zhao
Position Quality Engineer
e-mail address wenfeng.zhao@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

[NXP | Privacy Policy](#) | [Terms of Use](#)

NXP Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2010 NXP Semiconductors. All rights reserved.

Changed Orderable Part#	Changed Part 12NC	Changed Part Number	Changed Part Description	New Orderable Part#	New part 12NC	New Part number
PCA9450AHNY	935386091518	PCA9450AHN	PMIC for i.MX8M Mini(845S)	PCA9450AAHNY	935410198518	PCA9450AAHN
PCA9450CHNY	935386093518	PCA9450CHN	PMIC for i.MX8M Plus(865S)			
PCA9450BHNY	935386092518	PCA9450BHN	PMIC for i.MX8M Nano(815S)			