

Product Discontinuation Notice

January 2013

Discontinuation of F4 (12,14,28,32,36,38,48,66 pin) Narrow Pitch Connector



1. Reason: Low market demand

2. Affected parts:

AXK7L12223G (Socket)	AXK7L36223G (Socket)
AXK8L12124BG (Header)	AXK8L36124BG (Header)
AXK7L14223G (Socket)	AXK7L38223G (Socket)
AXK8L14124BG (Header)	AXK8L38124BG (Header)
AXK7L28223G (Socket)	AXK7L48223G (Socket)
AXK8L28124BG (Header)	AXK8L48124BG (Header)
AXK7L32223G (Socket)	AXK7L66223G (Socket)
AXK8L32124BG (Header)	AXK8L66124BG (Header)

3. Last time buy: End of September 2013

4. Substitution: Contact your local Panasonic sales representative

Any questions, please contact your local Panasonic Sales representatives.

(Ref#: T-1289-11)