



Product Change Notification

TE Connectivity

Product Change Notification: P-19-017913

PCN Date: 19-SEP-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).


General Product Description:

TE UPM RA Power Connector Printing Content Change

Description of Changes

TE UPM RA Power Connector Printing Content Change, to add the part number in product printing content, which will be better to distinguish the connector part with similar structure in actual application. The old printing content is only date code, and the new printing content will be part number and data code. Detail please refer to the attachment with comparison view before and after change.

Printing Before Change



Printing After Change



Other attachments:

[TE UPM RA Power Connector Printing Change_20190919](#)

Reason for Changes:

Customer Request.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

20-SEP-2019

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

31-DEC-2019

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
120954-1	NO						
120955-1	NO						
120956-1	NO						
120957-2	NO						
120958-1	NO						
5-5223961-1	NO						
5-5223963-1	NO						
5223961-1	NO						
5223962-1	NO						
5223963-1	NO						
5646956-1	NO						
5646956-2	NO						
5646957-1	NO						
5646958-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
120954-1	NO						
120955-1	NO						
120956-1	NO						
120957-2	NO						
120958-1	NO						
5-5223961-1	NO						
5223962-1	NO						
5646956-1	NO						
5646958-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-5223963-1	NO						
5646956-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
120954-1	NO						
120955-1	NO						
120956-1	NO						
120957-2	NO						
120958-1	NO						
5-5223961-1	NO						
5-5223963-1	NO						
5223962-1	NO						
5646956-1	NO						
5646958-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-5223963-1	NO						
5223961-1	NO						
5646956-1	NO						
5646956-2	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5646957-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-5223963-1	NO						
5223961-1	NO						
5223963-1	NO						
5646956-1	NO						
5646956-2	NO						